Certificate number: o60247279i246287-A-1



Calibration Certificate





Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US Laboratory
Unfors RaySafe Inc.
2 Science Road
Glenwood, IL 60425-1586
USA
+1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product Serial number X2 R/F

Manufacturer

246287 RaySafe CALIBRATION INFORMATION

As found

12/27/2024

As left

12/31/2024 Yes

Adjustment done Tested by

Christina Arroyo

Tommy Cox

Approved by

Josefina Diaz

Finalization technician

Certificate date

1/8/2025

CALIBRATION RESULT

AS FOUND:

All measured and tested values of this certificate were found to be in conformance with the

specification.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air kerma: 5 %, Air kerma rate: 5 %

Time: 0.5 %, Voltage: 2 %





Certificate number: o60247279i246287-B-1



Calibration Certificate

Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US Laboratory
Unfors RaySafe Inc.
2 Science Road
Glenwood, IL 60425-1586
USA
+1-833-296-9240
customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product Serial number X2 R/F 246287

Manufacturer

RaySafe

CALIBRATION INFORMATION

As found As left

12/27/2024 12/31/2024

Adjustment done

Yes

Tested by

Christina Arroyo

Tommy Cox

Approved by

Josefina Diaz

Finalization technician

Certificate date

1/8/2025





Certificate number: o60248492i246430-A-1



Calibration Certificate





Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US Laboratory
Unfors RaySafe Inc.
2 Science Road
Glenwood, IL 60425-1586
USA
+1-833-296-9240
customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product

X2 MAM

Serial number Manufacturer 246430 RaySafe CALIBRATION INFORMATION

As found

2/4/2025

As left

2/5/2025

Adjustment done

Yes

Tested by

Christina Arroyo

Maria Isabel Magana Guerrero

Approved by

Josefina Diaz

Finalization technician

Certificate date

2/7/2025

CALIBRATION RESULT

AS FOUND:

One or more measured and tested values of this certificate are outside of the specifications by a margin less than the expanded measurement uncertainty. Therefore, it is not possible to state

non-conformance with specifications for those measurements.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air Kerma: 5 %

Voltage: 2 % or 0.5 kV (without paddle), 2 % or 0.7 kV (with paddle)





Certificate number: o60248492i246430-B-1



Calibration Certificate

Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US Laboratory
Unfors RaySafe Inc.
2 Science Road
Glenwood, IL 60425-1586
USA
+1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product Serial number X2 MAM 246430

Manufacturer

RaySafe

CALIBRATION INFORMATION

As found

2/4/2025 2/5/2025

As left

Yes

Adjustment done Tested by

Christina Arroyo

Maria Isabel Magana Guerrero

Approved by

Josefina Diaz

Finalization technician

Certificate date

2/7/2025





Certificate number: o60247105i229999-1



Calibration Certificate





Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US Laboratory
Unfors RaySafe Inc.
2 Science Road
Glenwood, IL 60425-1586
USA
+1-833-296-9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product

X2 Survey

Serial number Manufacturer 229999 RaySafe

CALIBRATION INFORMATION

As found

12/18/2024

As left

12/18/2024

Adjustment done Tested by Yes Armad Bryant

Approved by

Josefina Diaz

Finalization technician

Certificate date

1/8/2025

CALIBRATION RESULT

AS FOUND: All measured and tested values of this certificate were found to be in conformance with the

specification.

AS LEFT: All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air kerma: 5 % (RQA), 10 % (N-series)





Certificate number: o60247196i256791-1



Calibration Certificate





Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US Laboratory
Unfors RaySafe Inc.
2 Science Road
Glenwood, IL 60425-1586
USA
+1-833-296-9240
customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product

X2 CT

Serial number Manufacturer 256791 RaySafe CALIBRATION INFORMATION

As found

12/20/2024

As left

12/20/2024

Adjustment done

Yes

Tested by

Armad Bryant

Approved by

Josefina Diaz

Finalization technician

Certificate date

1/8/2025

CALIBRATION RESULT

AS FOUND: All measured and tested values of this certificate were found to be in conformance with the

specification.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Air kerma: 5 %





Certificate number: o60247364i232789-1



Calibration Certificate

Customer UPSTATE MEDICAL PHYSICS BLOSSOM DR 1290 14564 VICTOR US Laboratory Unfors RaySafe Inc. 2 Science Road Glenwood, IL 60425-1586

USA

+1 - 833 - 296 - 9240

customerservice.us@raysafe.com

CUSTOMER INSTRUMENT

Product Serial number X2 Light 232789

Manufacturer

RaySafe

CALIBRATION INFORMATION

As found

1/2/2025

As left

1/2/2025

Adjustment done

Yes

Tested by

Amber Ramos

Approved by

Josefina Diaz

Finalization technician

Certificate date

1/8/2025

CALIBRATION RESULT

AS FOUND:

One or more measured and tested values of this certificate are outside of the specifications by a

margin less than the expanded measurement uncertainty. Therefore, it is not possible to state

non-conformance with specifications for those measurements.

AS LEFT:

All measured and tested values of this certificate were found to be in conformance with the

specification.

Relevant instrument specifications

Illuminance: 3 % Luminance: 3 %



